

RECEIVED NV3-215

1003 HAY 12 A 10: 26

**VIA FACSIMILE** May 9, 2003

OFFICE OF DEFECTS INVESTIGATION

Poreche Cars North America, Inc.

980 Hammond Drive Suite 1000 Atlanta, Gaurgia 20928

1-800-PORSCHE

03V-004 Amendment

Ms. Patricia Wallace Safety Defects Analyst National Highway Traffic Safety Administration 400 Seventh Street, S.W. Washington, D.C. 20590

RE: Updated Recall Notification Report for the Porsche Boxster/Boxster S

Dear Ms. Wallace:

On behalf of Dr. Ing. h.c.P. Porsche AG, Porsche Cars North America, Inc. has enclosed an updated Defect Information report pursuant to the provisions of Part 573 of Title 49 of the Code of Federal Regulations. Please note that we have expanded the recall to include a few (25) model year 2003 Boxster and Boxster S models produced before the production break.

Should you have any questions or require further information, please do not hesitate to contact me at (770) 290-3627.

Sincerely.

Walter J. Lewis, Manager

Regulatory Affairs

Enclosures:

## PORSCHE

03V-004 Amendment

## Update PART 573 Defect and Noncompliance Report

On January 14, 2003, Dr. Ing. h.c.F. Porsche AG determined that a defect, which relates to motor vehicle safety, exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

May 9, 2003

Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

Manufacturer

Agent

Manutacturer Dr. Ing. h.c.F. Porache AG 70435 Stuttgart Germany

Date this report was prepared:

Agent General Counsel Porsche Cars North America, Inc. 980 Hammond Drive Suite 1000 Atlanta, GA 30328

Corporate official, whom the agency should contact with respect to this recall:

Walter J. Lewis, Manager Regulatory Affairs Tel. No: (770) 290-3627 Fax No.: (770) 290-5508

Name of Person who prepared this report: Walter J. Lewis

Signed:		
JIKI BU.		



# Update PART 573 Defect and Noncompliance Report

- Identify the Vehicle Models involved in the Recall
- Vehicles Involved in the Recall:

Make:

**Porsche** 

Model Years:

1997 - 2003

Models:

Boxster (model year 1997 to 2003), Boxster S (model year 2000 to 2003)

Production Dates:

SOP to May 15, 2002.

VIN Ranges:

See page 1 of the enclosed draft Campaign Information

bulletin.

Vehicle Type:


Passenger Car

Bodystyle:

Two-door convertible

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents.

Approximately 7% of the above automatic transmission equipped (Tiptronic) vehicles produced during the above production dates maybe affected by this recall.



# Update PART 573 Defect and Noncompliance Report

- II. Identify the Recall Population
- 3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

Total Number Potentially Affected by the Recall:

12,234

4. Approximate percentage of the total number of vehicles above estimated to actually contain the defect or noncompliance:

7%

Identify and describe how the recall population was determined:

Ouring routine internal quality audits the problem was discovered in several company vehicles in Germany.



## Update PART 573 Defect and Noncompliance Report

- III. Describe the Defect or Noncompliance
- 5. Describe the defect or noncompliance.

The affected vehicles may have been produced with an incorrectly adjusted automatic transmission lever cable. If the cable is incorrectly adjusted it may be possible to shift out of park after the ignition key has been removed from the ignition.

Describe the cause of the defect or noncompliance condition.

See above.

Describe the consequence of the defect or noncompliance condition.

It maybe possible to knock the transmission lever out of the park position after the key has been removed.

identify any warning, which can (a) precede or (b) occur.

Not applicable.

Identify the supplier by corporate name and address, and the name and title of the chief executive officer or knowledgeable representative of the supplier:

Not Applicable.

May 9, 2003 Page 4 of 8



# **Update PART 573 Defect and Noncompliance Report**

- IV. Provide the Chronology in Determining the Defect/Noncompliance
- 6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

To be determined.

7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

Not applicable.

May 9, 2003 Page 5 of 8

### PORSCHE

03V-004 Amendment

## Update PART 573 Defect and Noncompliance Report

### V. Identify the Remedy

8. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

The vehicles will be recalled to dealership for inspection of the cable adjustment and corrected if necessary. Please refer to the attached Campaign information bulletin for the exact repair procedure.


Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

### Not applicable.

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

During the model year changeover there were substantial revisions to the factory assembly instructions. Fortuitously, these revisions to the assembly instructions remedied the problem in production.

May 9, 2003 Page 6 of 8




# Update PART 573 Defect and Noncompliance Report

### VI. Identify the Recall Schedule

Furnish a schedule or agenda (with specific dates) for notification to dealers and purchasers.

We wish to notify our dealers beginning on May 12, 2003 and begin the mailings to owners on May 14, 2003.



# Update PART 573 Defect and Noncompliance Report

### VII. Furnish Recall Communications

9. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification.

Please refer to the attached Campaign information buildtin for the exact repair procedure. Page 4 of the buildtin contains a sample customer notification letter.

May 9, 2003 Page 8 of 8

## PORSCHE'

# DRAFT

# Campaign Information

Boxster

A305

3715

3

A305 - Checking Adjustment of the Tiptronic Keylock Cable

Binder - Camp., Lit., Trein., Werr.

#### Attentions

### Bales Manager, Service Manager, Parts Manager, Service Technician

#### Information:

This is to inform you of a voluntary Customer Recall Compeler Involving a certain range of 1998 through 2003 model year 986 Boxster and 986 Boxster S vehicles.

Porsche AG, the manufacturer, has initiated this Customer Campaign Action relating to Boxster and Boxster S vehicles with Tiptronic transmission that were produced with an incorrectly edjusted key-lock cable down to the shift selector.

If the key-lock cable is not adjusted correctly, it is possible that the ignition key will shag upon being removed from the ignition lock or the selector lawer can be shifted from position "P" with the ignition key removed and the locking button operated.

If the selector lever is then shifted from position P to position R, N or D with the vehicle parked, and if the parking brake is not on, the vehicle will not be secured from hadvertently rolling away.

In order to avoid a dangerous situation, the key-lock-cable function must be checked and, regardless of the result of this check, the key-lock cable must also be adjusted.

A total of 12,234 U.S. and 415 Canadian vehicles fall within the scope of this recall campaign.

Very Important. Use the VIN range below as a general guideline. The VIN can be checked in the Porsche e-DCS/WWS for confirmation of an open recall campaign.

The affected Vehicle Identification Numbers are contained in the following VIN-Ranges, categorized by model year:

#### **US and Canadian Vehicles**

MN'98 (W) - From WPOCA2989WU620068 to WPOCA2987WU626452 Boxeter (U.S.)

MY'98 (W) -- From WPOCA2981WU620291 to WPOCA2981WU625829 Boxster (Canadian)

MY\*99 (X) - From WPOCA2987XU620121 to WPOCA2989XU633730 Boxster (U.S.)

MY 99 (X) - From WPQCA2982XU621Q46 to WPQCA2986XU633345 Boxester (Canadian)

MYCO (Y) - From WPOCA2981YU620066 to WPOCA2980YU628501 Boxster (U.S.)

MY'00 (Y) - From WPOCB2988YU660061 to WPOCB2981YU665070 Boxeter S (U.S.)

MY'00 (Y) - From WPOCA2980YU620270 to WPOCA2987YU628396 Bonster (Canadian)

MYOC (Y) - From WPOCB2982YU660170 to WPOCB2988YU664739 Boxster S (Canadian)

MY'01 (1) ~ From WP0CA29811U620073 to WP0CA29851U627642 Boxster (U.S.

MY'01 (1) - From WPGCB29831D660068 to WPOCB29841U665473 Boxster S (U.S)

MY'01 (1) - From WP0CA29891U620144 to WP0CA29891U627417 Boxster (Canadian)

MY'01 (1) - From WPOCB29871U660137 to WPOCB29831U664489 Boxster S (Canadian)

MY'02 (2) - From WPOCA29852U620062 to WPOCA29862U626100 Boxster (U.S.)

MY02 (2) - From WP0CB29822U660063 to WP0CB29832U664316 Boxster S (U.S.)

MY'02 (2) - From WPOCA29892U620128 to WPOCA29872U625294 Boxster (Canadian)

MY'02 (2) ~ From WPQCB29882U660116 to WPOCB29822U664159 Boxster S (Canadian)

MY'03 (3) - From WPOCA29853U620063 to WPOCA29833U620109 Boxster (U.S.)

MY'03 (3) - From WPOCB29863U660066 to WPOCB29843U660079 Boxster S (U.S.)

MY'03 (3) - Only WPOCA29893U620096 Boxster (Canadian)

## PORSCHE'



3 Boxster 3715 A305

Campaign Information

### informations/cont'd) Customer Notification

Porsche Cers North America, Inc., will notify All Owners of affected vehicles by First Class Mail during the week of May 1.2, 2003. See enclosed copy of the Recall Notification card to the Porsche Owner. A fisting of affected VINs (with owner name and addresses) will be sent to you.

If a vehicle within the affected ViN range is in your dealership for repair/service, or your dealer inventory, the Recall Campaign must be performed immediately.

Work Procedure: See Attachment "A"

Parts Information: None

Time Allowance: Scope Time Units Description

1 10 TU Chack keylock cable adjustment 2 50 TU Check and adjust keylock cable

Administrative

Procedure: Soe Attachment "E"

## PORSCHE!

Compaign Information	Boxster	7
Campaign Information	A305 3715	J

Following completion of the recall, please enter this information into the Maintenance Booklet (see sample below).

		<del></del>
	☐ Yearly Melvierance	☐ Yakety Mahdunyaka
-Civerance	☐ Mhor Naitheannise	□ Minor Miljiriananta -
	☐ Major Maintassea	Disper Makesmarks
Committee could be the second	Francisco Control Melateriano	Enfaction Control Matriconance
\$/12/2003 A305	<u> </u>	Case
yje, 7200	Maria Caracteristics of the Caracteristics o	16e
(deciar states)	kinder stangs	(distinct statement
☐ Yearly Mirrhardina	The sty Multiple rates	☐ youth pingranace
Minor Mulatersence	☐ Magair Makinganyangan	D plints Nationalism
☐ Major Mebiterianos	☐ Major Meissans—ca	☐ Mojer Glebalpasines
Earlision Control Maintenance	Carries Fiere Covered Maintenance	Enlados Corpro Minimumos
Date	<u>Date</u>	Die
<b>188</b>	Ws	Mine .
Steeler stampt	idealor sisrupi	(designat effectropi)
L	I	1

THE in data and milesope. Only elpoid off type of service perferond.

Silelel
d Innical Service

inspectant. Nation: Person Cars NA Technical Indians are betted for use by archeologic technicists, not a "Dobycorpatian". They are written as system than trans incidence of conditions that may accur on more variable, or parties are personal transpectation of conditions and continued in the most proper content of personal transpectation of personal transpectations are recommended in these builds may be deviated to the sale operator of personal transpectation from the property and activities in the personal transpectation of personal transpectations are the personal transpectation of the personal transpectation of

					MANO MIN	** ****	71 75 K-4, IIIA		-
Designation	Sanice Menager	- Shap Foremen		Struige Technisian					
Routing	Aust. Marager	Westerny Admin		Savice Technician					_
Parade, the Paradie only, P	woch Disign, Bouler, Cames, 911. ie	nda, Cayona, Puradhi Ciyah	m, POCS, PCM,	PCN, eQCS, Technolos, T	tguernent, Tipo	rode, WrisCh	s, Vandige, <sup>1</sup>	Weggers and the di-	,

PORTION OF PATISON OFFICE PRODUCT CONTROL STATE AND THE STATE OF THE PARTIES OF T

3 3715

Boxster A305

Campaign Information

#### **Customer Notification Card**

### Customer Campaign Notice

#### Cour Persons Dente:

This notice is being seed to you in accordance with the requirements of the National Traffic and Motor Which Saliety Act.

Porsche AG, the measuracture, has determined that a defect relating to motor vehicle setmy exists in certain model year 1956, through 2003 Beautier and Beautier 6 vehicles.

Our necestis indicate that you are the Owner of a Porectic Bosster or Bosster 9 Tigarcels which involved in this recall exempting.
Your vehicle may have been produced with an incorrectly adjusted key-lock-cable show to the shift selector. If the key-lock-cable is not adjusted correctly, it is possible that the ignition key will energ upon being removed from the ignition last or the selector leave can be shifted from position T' with the ignition key removed and the lockest setted operated.

If the selector lever is then shifted from position if to position is. It or D with the which parties, and if the parting brains is not un, the vehicle will not be accurate from inservorsarily reling seety.

in order to avoid a dangerous situation, the lay-lack-cubic function trust by checked ond, regardless of the results of this check, the toy-lock-cubic must also be adjusted.

You should arrange for an appointment with your Porschy dyalor as soon as possible to have the required repair performed. The separatry topic to perform this recall will be available at the Porsche dealer of your choice. Perts should not be required for this chack. The estimated time to perform this recall comparing is apprecipately one your Please allow your tell and your Porsche dealer additional time to complete the retains.

If your Porache dualer is unable to perform this repair within a reasonable extint of time, you may call or write:

Porseke Care North America, Inc. 980 Hammond Drive, Salta 1000 Alberta, Georgia 30328

Attention: Customer Commitment

Tariaphone: 1 (800) - Poreche (1 800 767-7243)

If you have already paid for your vehicle to be repaired for this particular problem, you will still need to have your vehicle inspected. However, the costs that you previously incurred may be reimbersuitle to you. Please contact Persobe as the Customer Commitment telephone municipe issued above.

We absurely regret any incorrections this Cestomer Compaign may cause, and tops you understand our interest in performing this work promptly so that you can be catisfied with your Poracle automobile. There are no costs to you and the repair is inso-originately legge accept our application for this suplement service visit.

Sincersiy.

Porsche Cars North America, Inc.

if you as longer own dis retornable or your address in different from that shown below, please correlate this postugal oranged card, debuth and relum. Thurk you for your assistance.

(i) by contact editions in: or	C 4 sold this volitie has	
Last hume	First Mane	initi
Nymbys Street		
T		7- M-
	944	
□ Valdide lettinsf/sc/anderic 1	L Discounts	
— — — — — — — — — — — — — — — — — — —	F L-1-1-1-1-1 by the last the same of the	Panel .
<ul> <li>Vehicle reporting status:</li> </ul>		Ame AOEA
	Plant They Tible print put give controlled.	A305

Thook you for 5 your reply.

The Tiptomic keylock cable function will be checked and adjusted if any exemy.

FPED - 3 1 042

# 605264度,

**DRAFT** 

Campaign Information

Boxster A305

3715

3

### **Customer Notification Card**

Portuche Care North Agenton, Inc. 900 Hammand Drive, Sales 1900 Americ, Marylle 306326	
	ner Campaign Notice
- Valdelinger Pauster Paus des palementalisations Pormaine Andre als pour marings.	A305
<b>,</b> æ	3H>>5 <b>2</b> C-4
Diane you for your reply.	HE PUSING HAND
The liptoms, lecylock called function will be disclosed and seading telephone adjusted three controls.	BUSINESS REPLY CARD PROT GUESS PERMIT NO. 15220 POLATIO, AN POSTING WILL BE MOD IT ADMICEST.  Por sche Cara North America, Inc. 980 Hammond Ortva Suite 1000 Attanta, Georgia 30328-9735
VEN TO CONTENT	halidani kalidala kalidala kalida kal

Boxster 3715 A305

Campaign Information

#### Attachment "A"

Tooks Required:

Medium slotted screwdriver

Work Procedure: Follow the Work Steps in Table 1 to determine if corrective action is necessary.

Work Stop	<u>                                     </u>	f medien/Teg	outline O.K.	No C.K. contlavo with
•	ignition lary is removed and selector lover is in position "F"	Starting point		
	Autuma ipclurg butten of selectar lawer and attempt to move selectar lawer out of Marr pooklim	Lacking button of solecter lever rount be locked and selector lever rount upt be able to be moved out of "P" periodo.	·c-	Sup 2
٥	Hold down tooking button at palestor labor, ironit lightion key in Ignition lock and turn to	tgetien book position I to not able to		
	the right from the "O" position until the looking button can be lefty actuated	ignide <u>e retrains policitud</u> ell Lacking berson of sulector leaver can be accusable completely	יסי	Step 2
Ь	More selector jever to position "D"-	Selector lever can be proved	-Ea	Step 2
E	Leging selector layer in "D" position, continue with work one "T"			_
F	Durn ignition hay to the left until stup and see it ignition key can be pulled out	ignition key abouted not be able to be pulled out	-6-	Rap 2
	Put selector lever in "P" position, continue with work stee "H"			
Н	Turn ignition key to the left to the "O" position and see it is too too too perfect sur	ignition hay must be able to be pulled out	יני.	Step 2
1	Leave expecter lever in "P" position, continue with work edge "J"			
J	Actuate locking button of exiscitar lever and attempt to move culector lever	Locking button of mineter lever must be able to be moved out of "P" peaking	7K* ·	Brep 2
ĸ	Function that CK	First fenction test	Step 14	
		Every salelli lount treasper best	Open 11	

Table 1

- 1. Function test. Follow steps A to K in Table 1.
- 2. Remove selector lever handle according to the Technical Manual, Group 3, Chapter 37 04 19.
- 3. Remove cover (I, Figure I) on the front, left and right in the footwell according to the Technical Manual, Group 6, Chapter 68 17 19. (Figure 1 shows the vehicle with manual transmission)
- Remove cover plate on selector lever support.




Figure 1

## PORSCHE'

DRAFT


# Campaign Information

Boxster A305


3715

# (cont'd)

- Work Procedure: B. Unlock the red locking U-Cilo (2, Figure 2), to do this, press the lugs of the red locking UCIp inwards and at the same time, push locking button upward (B, Figure 2). importanti Only lift the red locking U-Cilp far enough to allow the cable to move freely. It is very hard to reinstell the clip if it is completely removed.
  - Move selector lever to position "P"
  - Press cable sleeve (3. Figure 2) toward the selector. lever.
  - Quickly release the cable sleeve (3, Figure 2). Only quickly releasing the cable sleave will use the pre-tension force of the spring (not shown in figure) to correctly adjust the keytock cable.







12. Install cover (1, Figure 1) on the front, left and right in the footwell according to the Technical Manual, Group 6, Chapter 68 17 19.

13. Install selector lever handle according to the Technical Manual, Group 3. Chapter 37 04 19.

14. Enter the campaign into the Maintenance booklet.

Literature:

Bexster/S Technical Manual, Group 3:

37 Q4 19 - Removing and installing selector knob > Repairs: 37 08 19 - Removing and installing selector support > Repairs:




Figure 2

Boxster 3715 A305

Campaign Information

Attachment "8"

Administrative Procedure, Recall A305

Checking the adjustment of keylock cable

Warranty claims should be submitted via e-DCS

Note: Always check for open recall status under the appropriate e-DCS menu options.

Affected VINe:

See customer notification page

**Warranty Code:** 

R

Damage Code:

A305 099 000 1 (for A305)

Labor Operation:

Will be automatically inserted along with the necessary parts when the damage code is entered.

Repair Code:

1

Time Units:

Scope	Time Units	Description
1	1010	Checking the locking cable adjustment per Table 1
2	£01U	Checking and adjusting the locking cable

### Parts information: None

In cases where the recall cannot be performed, submit this information on a claim via e-DCS with the appropriate disposition code by inserting the code in the last digit of the damage code, as shown bellow.

### Disposition/Repair Code

- 3 Total Loss
- 4 Vehicle Stolen
- S Vehicle left North America.
- 6 Customer Moved/address unknown
- 7 Vehicle sold, new owner information.
- 9 Customer refused to comply

#### Owner Name and Address Change

If the owner name and address are shown incorrectly, submit a correction using the name/address postcard from the Warranty Maintenance Booklet (or Recall mailing), or report the change to the Warranty Department via e-DCS, including VIN.